


Repair kit magnetic coupling ALP-0165 – 0280

Note The repair kit contains only the numbered parts and is only supplied complete.



| Qty. | Pos. No. | Part | Qty. | Pos. No. | Part |
|------|----------|-----------------|------|----------|-------------------|
| 1 | 053 | Coupling hub | 1 | 739.2 | O-ring |
| 1 | 063 | Supporting ring | 4 | 914.5 | Socket screw |
| 1 | 515 | Outer rotor | 1 | 917 | Countersunk screw |
| 1 | 518 | Inner rotor | 2 | 917.1 | Countersunk screw |

Tab. 1: Repair kit magnetic coupling ALP-0165 – 0280